## Oil Field Environmental Incident Summary

**Responsible Party:** CITATION OIL & GAS CORP. **Well Operator:** CITATION OIL & GAS CORP.

Well Name: BRANDJORD 5H

Field Name: CIMBEL Well File #: 14646

Date Incident: 12/16/2013 Time Incident: 0645 Facility ID Number:

County: BOTTINEAU Twp: 163 Rng: 78 Sec: 20 Qtr: SW SE

Location Description:

Submitted By: LINDSEY SCHEFFER Received By:

Contact Person: LINDSEY SCHEFFER

14077 CUTTEN ROAD

PO BOX 690688

HOUSTON, TX 77269-0688

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike					Reported to NRC:	No	
	Spilled	Units	Recovered	Units	Followup	Units	
Oil	20	barrels	16	barrels	16	barrels	
Brine	0	barrels	0	barrels			
Other	0	barrels	0	barrels			

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 9/27/2016 Clean Up Concluded: 12/20/2013

Risk Evaluation:

Areal Extent:

## Potential Environmental Impacts:

## Action Taken or Planned:

SHUT WELL IN, CLOSED VALVES TO OIL TANK. HAD HOT OIL TRUCK SUCK UP WHAT HE COULD AND PUT OIL BACK INTO OIL PRODUCTION. CLEAN OUT TANK AND REPAIR IF POSSIBLE IF NOT REPLACE TANK.

Wastes Disposal Location:

Agencies Involved:

## **Updates**

Date: 2/5/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.